TO: Mayor via City Secretary REQUEST FOR COUNCIL ACTION SUBJECT: Appropriate funds to the In-House Renovation Revolving Fund to address Page Agenda Facility Condition Assessment (FCA) Priority 1 & 2 Deficiencies during FY2016 for the 1 of 2 Houston Fire Department (HFD) Item WBS No: C-000193-0003-4-01-01 FROM (Department or other point of origin): **Origination Date Agenda Date** General Services Department Council District(s) affected: **DIRECTOR'S SIGNATURE:** A, B, C, D, E, F, G, I, J, K Scott Minnix Munix For additional information contact: Date and identification of prior authorizing Jacquelyn L. Nisby Phone: 832 393-8023 Council action: RECOMMENDATION: Appropriate bond funds to the In-House Renovation Revolving Fund (Fund 1003) for completion of FCA Priority 1 & 2 Deficiencies for various HFD facilities during FY2016. **Amount and Source of Funding: Finance Budget:** \$721,000.00 - Fire Consolidated Construction Fund (4500) SPECIFIC EXPLANATION: In 2013, Parsons Commercial Technology Group, Inc. conducted a comprehensive FCA on 421 City facilities, which identified and prioritized building deficiencies. The FY2014-2018 Capital Improvement Plan includes the most critical repairs identified in the FCA report as Priority 1 & 2 deficiencies. These deficiencies require immediate attention because they have created, or will soon create, conditions that are safety hazards, are in extreme or accelerated deterioration, or can result in failing and interrupted operations. The General Services Department (GSD) recommends that City Council appropriate \$721,000.00 out of the Fire Consolidated Construction Fund to the In-House Renovation Revolving Fund to address the FCA Priority 1 & 2 deficiencies for the HFD facilities listed below. GSD's In-House Renovation Group provides labor and expertise required to address serious maintenance deficiencies by performing capital improvements to city facilities and emergency repairs affecting life safety issues. PROJECT DESCRIPTION: FCA repairs generally include electrical, plumbing and concrete repairs. Electrical work is primarily lighting and electrical transformer testing. Plumbing work consists of back flow preventor and hot water circulating pump replacements. Concrete repairs include parking and sidewalk repairs. PROJECT LOCATIONS: The FY2016 FCA Priority 1 & 2 deficiencies projects are as follows: **FIRE DEPARTMENT** 2215 W. 43<sup>rd</sup> 1. Fire Station No. 13 451M Dist. C Replace Failing Concrete 2. Fire Station No. 83 3350 Breezewood 489X Dist. F Generator Upgrade 3. Fire Station No. 69 1102 W. Belt 489R Dist. G **New Metal Roof** 4. Fire Station No. 73 9640 Wilcrest 529U Dist. J Replace Kitchen Cabinets 5. Fire Station No. 7 1402 Elgin 493T Dist. D **New Air Compressor** 6. Fire Station No. 46 3902 Corder Dist. D 533Q Correct Electrical Panel 7. Fire Station No. 48 11616 Chimney Rock 571B Dist. K Replace Smoke Detectors 8. Fire Station No. 56 5820 E. Little York Correct Electrical Panel 412V Dist. B REQUIRED AUTHORIZATION CUIC ID# 25KA07 General Services Department: **Houston Fire Department:** Chest

Rodney West

Interim Fire Chief

Richard Vella

Assistant Director

DATE:	SUBJECT: Appropriate funds to the In-House Renovation Revolving Fund to address Facility Condition Assessment (FCA) Priority 1 & 2 Deficiencies during FY2016 for Houston Fire Department (HFD) WBS No: C-000193-0003-4-01-01	Originator's Initials KA	Page 2 of 2
-------	---	--------------------------------	----------------

## **PROJECT LOCATIONS cont:**

9. Fire Station No. 61 10. Fire Station No. 64 11. Fire Station No. 66 12. Fire Station No. 72 13. Fire Station No. 76 14. Fire Station No. 80 15. Fire Station No. 82	9726 Monroe 3000 Greens Rd. 5800 Teague 17401 Saturn Ln. 7200 Cook Rd. 16111 Chimney Rock 11250 Braesridge	575L 374N 450A 618Q 529J 611B 530Y	Dist. D Dist. B Dist. A Dist. E Dist. F Dist. K Dist. K	Replace Smoke Detectors Replace Failing Wiring Repaying Parking Lot Correct Electrical Panel Replace Smoke Detectors Correct Electrical Panel Replace Smoke Detectors
16. Fire Training Academy	8030 Braniff	575K	Dist. K	Replace Smoke Detector's Replace Failing Concrete:

SM:JLN:RV:KA:gf

c: Marta Crinejo, Jacquelyn L. Nisby, Richard Vella, Keith Andrews, Ja'nice Sparks, Mary Villarreal, Mark Donovan, Rodney West