



W#	Well Name	Address	Key Map	Council District	Council Member
8	Park Ten Well 4	14315 Park Row Blvd.	488W	A	Brenda Stardig

**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**



Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, © OpenStreetMap contributors, and the GIS User Community



W#	Well Name	Address	Key Map	Council District	Council Member
6	Jersey Village Well 4	7012 Mayard	408R	A	Brenda Stardig


▲ Project Site

WSP


0 750 1,500 3,000 Feet

**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, © OpenStreetMap contributors, and the GIS User Community




W#	Well Name	Address	Key Map	Council District	Council Member
2	Spring Branch Well 4A	4105 Campbell	450K	A	Brenda Stardig




**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, © OpenStreetMap contributors, and the GIS User Community




W#	Well Name	Address	Key Map	Council District	Council Member
3	Acres Homes Well 2A	1810 Dolly Wright	412S	B	Jerry Davis




**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, OpenStreetMap contributors, and the GIS User Community




W#	Well Name	Address	Key Map	Council District	Council Member
4	Kingwood-3 Well 3	East End Park	298S	E	Dave Martin




**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, © OpenStreetMap contributors, and the GIS User Community






W#	Well Name	Address	Key Map	Council District	Council Member
9	District 111 Well 2	10301 Sun City Court	528V	F	Steve Le



**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, © OpenStreetMap contributors, and the GIS User Community



W#	Well Name	Address	Key Map	Council District	Council Member
11	District 21 Well 1	14322 Grisby	488A	G	Greg Travis


▲ Project Site

WSP


0 750 1,500 3,000 Feet

**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, © OpenStreetMap contributors, and the GIS User Community




W#	Well Name	Address	Key Map	Council District	Council Member
7	Southwest Well 10	4426 Southwest Fwy	491Z	G	Greg Travis




**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, © OpenStreetMap contributors, and the GIS User Community






W#	Well Name	Address	Key Map	Council District	Council Member
1	OST Acres Well 1	4022 Banner	455Y	I	Robert Gallegos



**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, © OpenStreetMap contributors, and the GIS User Community



W#	Well Name	Address	Key Map	Council District	Council Member
10	Southwest Well 4A	6002 Westpark	4911	J	Mike Laster


▲ Project Site

WSP

0 750 1,500 3,000 Feet




**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, © OpenStreetMap contributors, and the GIS User Community



W#	Well Name	Address	Key Map	Council District	Council Member
5	Sims Bayou Well 4	12445 Hodges	570M	K	Martha Castex-Tatum

▲ Project Site

**Location Map - Rehabilitation of Groundwater Wells**  
**WBS No. S-000200-0023-4**

Service Layer Credits: Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, OpenStreetMap contributors, and the GIS User Community