

| 4277-64 | Sanitary Sewer Cleaning and Television Inspection In Support of Rehabilitation | | | | |
|-------------------------|--|-------------------|-------|-------------------|-------------------|
| WBS No. R-000266-0174-4 | Sewer and Storm Maintenance, LLC | | | | |
| WORK ORDER | KEY MAP | SUBDIVISION | BASIN | Old Council Dist. | New Council Dist. |
| 4 | 449G | TIDEWATER CENTER | WW002 | A | A |
| 6 | 451S,W | GLENVIEW | IA015 | A | A |
| 8 | 450V | HOLLYWOOD GARDENS | IA031 | A | A |
| 11 | 449X | SHERWOOD ESTATES | SO202 | A | A |
| 12 | 449W,X,489A,B | WESTWICK | SO203 | A | A |
| 17 | 450H,M,451E,J | ROSSLYN GARDENS | NW172 | A | A |
| 20 | 447W,X,Y | PARK TEN | PT001 | A | A |
| 7 | 455G,H | CHATWOOD PLACE | FB017 | B | B |
| 14 | 531S,W | MAPLEWOOD SOUTH | SW250 | C | C |
| 2 | 534N,P,T | SOUTHCREST | SB107 | D | D |
| 5 | 574A,E | EDGEWOOD | CH015 | D | D |
| 10 | 533V,534S | SMALLWOOD TERRACE | SB082 | D | D |
| 13 | 534E,J | RIVERSIDE TERRACE | SB205 | D | D |
| 18 | 493X,533B,C | RIVERSIDE TERRACE | SB165 | D | D |
| 26 | 533Q,P | SOUTH UNION | BW251 | D | D |
| 22 | 336J | FOREST COVE | FD004 | E | E |
| 23 | 336K | FOREST COVE | FD006 | E | E |
| 24 | 336J | FOREST COVE T/H | MG003 | E | E |
| 27 | 489U,Y,Z,529D | WESTCHASE | BW251 | F | F |
| 1 | 413X | BURBANK GARDENS | II035 | H | H |
| 3 | 453C | BRIARCLIFF PLACE | II042 | H | H |
| 15 | 536P,Q,T,U | MEADOWBROOK | SBU04 | I | I |
| 19 | 535N,P,S,T | PARK PLACE | SB032 | I | I |
| 21 | 489U,Y,Z,529D | O S T ACRES | NE014 | I | I |
| 9 | 530S,T | CENTURY VILLAGE | KB324 | J | J |
| 16 | 571U,Y | MAYFAIR PARK | WE017 | K | K |
| 25 | 531W,X | PARKWEST | SW016 | K | K |
| 28 | 531W,571A | PARK WEST | SW018 | K | K |